



## AFF A800 の予期しないリブートと DIMM-XX での ECC エラー

https://kb-ja.netapp.com/on-prem/ontap/OHW/OHW-KBs/AFF\_A800\_unexpected\_reboot\_with\_ECC\_er... Updated: Sun, 09 Nov 2025 23:49:55 GMT

## 環境

AFF A800

## 問題

• 自動パートナー テイクオーバーを伴う予期しないノード リブートが原因で自動的にケースが作成されました。**例:** 

CLTFLT:HA Group Notification from node\_name (CONTROLLER TAKEOVER COMPLETE AUTOMATIC - Communication Error) ALERT

• システムメモリのエラ―によるパニック状態

ALERT sk.panic: Panic String: ECC error at DIMM-6:

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'