



NiCE

HTTPS証明書の更新がBrocadeスイッチに反映されない

https://kb-jp.netapp.com/on-prem/Switches/Brocade-KBs/HTTPS_Certificate_Update_does_not_take_e...

Updated: Wed, 28 Oct 2026 14:06:32 GMT

環境

- Brocadeスイッチ
- Fabric OS (FOS) 9.1.1x

問題

- 新しいHTTPS証明書のインストールに成功した後も、Webサーバーは古い証明書を提示し続けます。
- サービスの再起動を試みると、次のエラーで失敗します：

```
admin> hareboot
```

```
Can't do hareboot because system is not ready yet or other LS/HA config is in progress, rc=-1
```

- Errdumpはエラーを示しています：

```
[KSWD-1002], 205/96, FFDC | CHASSIS, WARNING, BrocadeG720, Detected termination of process mdd:2518., hasm_swd.c, line: 235, comp:insmod, ltime:2026/08/04-18:19:11:429243
```

```
[RAS-1001], 206/97, CHASSIS, INFO, BrocadeG720, First failure data capture (FFDC) event occurred., ffdcd.c, line: 1102, comp:raslogd, ltime:2026/08/04-18:19:11:430484
```

```
[RAS-5001], 207/0, CHASSIS, INFO, BrocadeG720, Message KSWD-1002 caused FFDC event, ffdcd.c, line: 1105, comp:raslogd, ltime:2026/08/04-18:19:11:430605
```

```
[HAM-1007], 217/98, FFDC | CHASSIS, CRITICAL, BrocadeG720, Need to reboot the system for recovery, reason: Software Bootup Failure:LS config timed out., hasm_iot.c, line: 1569, comp:hamd, ltime:2026/08/04-18:21:26:918053
```

```
[HAM-1009], 218/99, FFDC | CHASSIS, CRITICAL, BrocadeG720, Need to MANUALLY REBOOT the system for recovery - auto-reboot is disabled., hasm_iot.c, line: 1589, comp:hamd, ltime:2026/08/04-18:21:26:918293
```