



NiCE

NetApp Element Plug-in for vCenter Server (VCP) 4.7 を vCenter 6.5 に導入できません

https://kb-ja.netapp.com/on-prem/SolidFire/Element_OS_Kbs/NetApp_Element_Plug_In_for_vCenter_...

Updated: Fri, 23 Oct 2026 10:16:35 GMT

環境

- 管理サービス 2.18.91
- VMware vCenter Server (VCP) 4.7 の NetApp Element プラグイン
- VMware vSphere 6.5

問題

vCenter 6.5 環境で管理サービス 2.18.91 をインストールまたはアップグレードしたあとに NetApp Element

Plug-in for vCenter (VCP) 4.7 を登録した場合、プラグインコンポーネントは vSphere Web Client に表示されません。

/var/log/vmware/vsphere-ui/logs/vsphere_client_virgo.log でエラーが報告される

```
[2021-07-27T08:11:41.853Z] [ERROR] fs-watcher
org.eclipse.virgo.medic.eventlog.default DE0002E Installation of par
'com.solidfire' version '4.7.0' failed.
org.eclipse.virgo.kernel.osgi.framework.UnableToSatisfyBundleDependenciesException
Unable to satisfy dependencies of bundle
'com.solidfire-4.7-com.solidfire.vcp.solidfire-dataservice' at version '4.7.0':
Cannot resolve: com.solidfire-4.7-com.solidfire.vcp.solidfire-dataservice
Resolver report:
    An Import-Package could not be resolved. Resolver error data <Import-
Package: org.springframework.orm.hibernate5; version="0.0.0">. Caused by
missing constraint in bundle <com.solidfire-4.7-com.solid
fire.vcp.solidfire-dataservice_4.7.0>
    constraint: <Import-Package: org.springframework.orm.hibernate5;
version="0.0.0">
    An Import-Package could not be resolved. Resolver error data <Import-
Package: org.apache.mina.core.buffer; version="[2.0.0,3.0.0)">. Caused by
missing constraint in bundle <org.apache.sshd.core_0.5.0
.v201108120515>
    constraint: <Import-Package: org.apache.mina.core.buffer;
version="[2.0.0,3.0.0)">
    An Import-Package could not be resolved. Resolver error data <Import-
Package: com.solidfire.vcp.controller; version="0.0.0">. Caused by missing
constraint in bundle <com.solidfire-4.7-com.solidfire.v
cp.solidfire-war_4.7.0>
    constraint: <Import-Package: com.solidfire.vcp.controller; version="0.0.0">
with attributes {module_scope=com.solidfire-4.7}
    An Import-Package could not be resolved. Resolver error data <Import-Package:
com.solidfire.vcp.autoconfig; version="0.0.0">. Caused by missing constraint in
bundle <com.solidfire-4.7-synthetic.conte
xt_4.7.0>
    constraint: <Import-Package: com.solidfire.vcp.autoconfig; version="0.0.0">
constrained to bundle <com.solidfire-4.7-com.solidfire.vcp.solidfire-
dataservice> constrained bundle version range "[4.7.0,4.7.0]"
    with attributes {module_scope=com.solidfire-4.7}
```

.....

.....

[2021-07-27T08:16:46.873Z] [ERROR] plugin-deploy10 70000010 100005 200001
org.eclipse.virgo.medic.eventlog.default XF1009E Failed to deploy plugin
package 'com.solidfire' version '4.7.0'.

[2021-07-27T08:16:46.873Z] [INFO] vc-extensionmanager-pool-75 70000010 100005
200001 com.vmware.vise.extensionfw.impl.PackagesDeployer Processed deployment
failure for plugin package 'com.solidfire:4.7.0'.