



Eシリーズ E4000 controllerがコントローラ間通信障害を報告

https://kb-ja.netapp.com/on-prem/E-series/Hardware-KBs/E-series_E4000_controller_reporting_inter_c... Updated: Sun, 19 Oct 2025 15:03:57 GMT

環境

- NetApp Eシリーズ
- E4000
- StorageGRID アプライアンス

問題

- Recovery Guruが AUX ALT COMM LINK ERROR-Recovery Failure Type Code: 503を報告
- MAJOR-EVENT-LOG 重大イベントを報告

Event type: 1406

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'

Event category: Failure

Priority: Critical

Event needs attention: true

Event send alert: true
Event visibility: true

Description: Link issues have been encountered on an alternate controller

Ethernet channel

Event specific codes: 0/0/0 Component type: Controller

Component location: Shelf 99, Bay A

Logged by: Controller in bay A