



スイッチのアップグレード時に想定される SharedAndDedicatedSwitchToHA Alert

https://kb-ja.netapp.com/on-prem/ontap/MC/MC-KBs/SharedAndDedicatedSwitchToHA_Alert Updated: Tue, 04 Nov 2025 07:50:08 GMT

環境

- MetroCluster
- FAS/AFF

問題

• 以下は、スイッチのアップグレード中にトリガーされたヘルスアラートです。

Controller "Node_1" is connected to both the shared switch "switch_02" and the dedicated storage switch "switch_01". This configuration is not supported.

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'