



Brocade FCスイッチがシステム設定の解析に失敗してブートする

https://kb-ja.netapp.com/on-prem/Switches/Brocade-KBs/Brocade_FC_switch_boots_with_Failed_pars...

Updated: Sun, 19 Oct 2025 14:50:04 GMT

環境

- · Brocade G610 LW
- Fabric OS (FOS) v9.1.1b

問題

• スイッチのブートとログインは可能ですが、一部の設定が欠落しています:

```
Starting Fabric OS Services...
[wmd_init] Checksum does not match. current_cksum = 0x16c0388f stored_cksum = 0xcf25a6c1
FPGA version 0x82 reset rsn 0x01 updated reset rsn = 0x00
HW reset cause: first = 0x1 latest = 0x0
```

'NetApp provides no representations or warranties regarding the accuracy or reliability or serviceability of any information or recommendations provided in this publication or with respect to any results that may be obtained by the use of the information or observance of any recommendations provided herein. The information in this document is distributed AS IS and the use of this information or the implementation of any recommendations or techniques herein is a customers responsibility and depends on the customers ability to evaluate and integrate them into the customers operational environment. This document and the information contained herein may be used solely in connection with the NetApp products discussed in this document.'

```
Found 3(threshold 5) abnormal reboots within 3000 seconds
   window(threshold)
   Pre-existing WM Trace not found.
   sys lock debug init:wm pid hash table chunk size 409600.....
   bhpc irq init: Pcie domain 0 err interrupt handler Installed
   setting to MASTER as HA bit is not set
   GEN6 platform
   Existing reboot reason fsize=10 rb=
   HIL config loader completed: 0
   Failed parse system configs
   Fabric OS (example1)
   example1 login: admin
   Password:
   unknown(0):admin>
• switchshow、userconfig、alishow、errdump、supportshowなどのFOSコマンドが見つかりま
 せん:
   unknown(0):admin> switchshow
   -rbash: switchshow: command not found
• firmwareshow や clihistory などの FOS コマンドを実行:
   unknown(0):admin> firmwareshow
   Appl Primary/Secondary Versions
   _____
   FOS
         v9.1.1b
       v9.1.1b
• supportsave 実行されますが、supportshowを収集せず、エラーが表示されます:
   unknown(0):admin> supportsave
   This command collects only RASLOG, TRACE, core files, FFDC data
   and then transfers them to a FTP/SCP/SFTP server
   OK to proceed? (yes, y, no, n): [no] yes
   [\ldots]
   Saving support information:
   SLOT SWITCH
                                  CLI SIZE FILE SIZE CLI
        MODULE TIME LOAD AVERAGE
   TIME
                                   55.180 KB 0.000 KB 8.49450 secs
   CPO Switch0
                     RAS
   17.157818 secs 0.0/0.0/0.0
   CPO Switch0
                                  600.354 KB 1001.408 KB 7.938750 secs
                      INFRA
   10.741267 secs 0.1/0.0/0.0
   CPO Switch0
                     RASLOG
                                   78.795 KB 0.000 KB 0.273539
```

```
secs 1.11614 secs 0.2/0.1/0.0
*** Error in `/bin/rpm': free(): invalid pointer: 0x100277a0 ***
====== Backtrace: =======
/lib/libc.so.6(+0x7c7e0)[0xfc017e0]
====== Memory map: ======
00100000-00103000 r-xp 00000000 00:00 0 [vdso]
CP0
    Switch0
                   FABOS OFF 23.743 KB 0.000 KB 7.837862
secs 8.507474 secs 0.2/0.1/0.0
    Switch0
                   CORE FFDC
                                 0.000 KB 1884.448 KB 7.837862
CP0
secs 1.883398 secs 0.3/0.1/0.0
                                 48.266 KB 0.000 KB 1.938386
CP0
     Switch0
                   RAS POST
secs 2.633636 secs 0.3/0.1/0.0
Summary worker: 1, cpu load: 3 upload size: 3692 KB, time: 77 secs
upload: 1 load:0.3/0.1/0.0
SupportSave completed (FABOS is not ready) (Duration: 1 minutes 17
seconds).
```